



# Flushometer Care & Service 101

## Part 5: ESS Exposed Sensor Flushometers



# Presenters



**Dominick Pacione**  
Senior Field and Technical  
Support Technician  
Sloan Valve Company  
Franklin Park, IL



**Andrew Warnes**  
Technical Training Manager  
Sloan Valve Company  
Franklin Park, IL

# Agenda

## This presentation will cover:

- Overview of Sloan ESS Exposed sensor flushometers
- Most common field service issues and solutions
- Maintenance recommendations
- Summary
- Q&A

## We will not be covering:

- ESS TMO or ESS Concealed Service and Maintenance

Understand how to extend the service life of Sloan products



[Elmhurst Hospital Case Study, Elmhurst, IL USA](#)

# Acronyms in this Presentation

- **ESS** – Electronic Solenoid Sensor
- **TMO** – True Mechanical Override
- **OR** – Override Button
- **HW** – Hard-wired
- **WB** – Wall Box
- **SWB** – Small Wall Box
- **SBX** – Wall Plate with Integrated TMO  
aka “LaGuardia style”



# ESS Exposed vs. ESS Concealed



Royal ESS Exposed



Sloan/Regal ESS Exposed



Royal ESS 142 Concealed



ESS Concealed

# Why Specify A Sloan ESS Exposed Sensor Flushometer?

## New Installations

- Touch-free
- Simple to operate and maintain
- Shares many components with manual flushometers
- 24 VAC hardwired sensor operation (no batteries)
- Normally closed solenoid design (“mono-static”)
- Appearance

## Existing installations

- Utilizes existing 24 VAC power supplies
- Matches existing installed units
- Seamless replacement (since 1978)



# ESS Exposed Sensor Flushometer Applications



Water Closets



Urinals



Utility (Service) Sinks




Bedpan Washers




Squat Toilets

# ESS Exposed Sensor Flushometer Components

## CLOSET



## URINAL



All models use the EL-1500 Sensor Assembly



# What's the Difference?

Regal / Sloan Sensor Plate




Royal Sensor Plate



All ESS Wall Plates are designed to be screwed into electrical boxes. See the rough-in guide [HERE](#)

# ESS Exposed Sensor Flushometer Variations




Model	Type	Closet Wall Plate Sensor and Solenoid Plates	Urinal Wall Plate Combination Sensor and Solenoid Plate	Wall Plate Style	TMO True Mechanical Override Button	TMO Retrofit Kit	Power Supply
Royal	Diaphragm	Dual Plate	Single Plate	<b>Royal</b>	Optional	EL-1026A	24 VAC
Sloan	Diaphragm	Dual Plate	Single Plate	Regal/Sloan	Optional	EL-1026A	24 VAC
Regal	Diaphragm	Dual Plate	Single Plate	Regal/Sloan	Optional	EL-1026A	24 VAC
Crown	<b>Piston</b>	Dual Plate	Single Plate	Regal/Sloan	<b>NA</b>	<b>NA</b>	24 VAC

# How ESS Exposed Sensor Flushometers Function


[Link to ESS Exposed Sensor Flushometer Video](#)




Sensor scans for valid target




After valid target leaves, solenoid is energized



Solenoid movement permits water to flow into actuator cartridge and pushes plunger forward



Plunger tilts the relief valve, causing diaphragm to unseat and flush begins



Upper chamber re-pressurizes through the bypass, causing diaphragm to re-seat and ending flush

# How Do IR (Infrared) Sensors Work?



The EL-1500  
uses "Adaptive  
Sensing"

- Sensor activated flushometers use infrared (IR) technology
- Detects user and flushes when they leave
- Flushes as programmed
- Touch not required




Image courtesy of Scientifica Corbis

# EL-1500 and EL-1500L Series Sensor



	ESS
LED Color	Red
Start-up Time	1 minute
Start-up Indicator	Solid Red LED during start up
User is Detected	Slow flashing red LED, then rapid flashing red LED when unit is armed (ready to flush – 16s for closet and 8s for a urinal)
Flush Delay	Closet – 3s / Urinal – 1s
Low Battery Indicator	NA (Hardwired 24 Volt)
Link to Installation Instructions	<a href="#">ROYAL ESS</a>


# EL-1500 Sensor Tips

Indicator	Issue	Resolution
Continuous slow flashing red LED	Improper start-up	Disconnect power for 60 seconds and repeat installation procedure
Continuous fast flashing red LED	Sensor is detecting a target	Remove obstruction or clean sensor window
Red LED flashes an “SOS” pattern (three short, three long, three short)	Wiring connections are incorrect or there is an electrical short	Re-wire the sensor correctly and repeat installation procedure
LED lights do not function	No power to unit	Check power supply and repeat installation procedure




# Royal ESS Exposed Components Diagram

## Royal ESS Exposed Closet Flushometer




## Royal ESS Exposed Urinal Flushometer




[Royal ESS Exposed Install Guide](#)  
[Optima ESS Flushometer Repair & Maintenance](#)

# Regal/Sloan/Crown ESS Exposed Components Diagram

## Regal/Sloan/Crown ESS Exposed Closet Flushometer




## Regal/Sloan/Crown ESS Exposed Urinal Flushometer




[Regal/Sloan ESS Exposed Install Guide](#)  
[Crown ESS Exposed Install Guide](#)  
[Optima ESS Flushometer Repair & Maintenance](#)

# ESS Exposed Sensor Flushometer Wiring Diagram

## Single Unit




## Multiple Units



# Field Issues & Solutions

from most common to least common



Images of uncommon “self-inflicted” issues

# Dominick's General Troubleshooting Approach for ESS Exposed Sensor Units



Sensor Assembly (and  
Override Button)



Solenoid



Actuator Cartridge



Diaphragm

# No Flush



Sensor



Solenoid



Actuator cartridge

Symptom	Cause	Solution
Sensor LED blinks but does not flush, Override Button works	Sensor not calibrated	Power off for 60 seconds, power on again for sensor to auto adjust for 60 seconds, do not block sensor
Sensor LED does not blink or activate flush, Override Button works	Sensor damaged	Replace EL-1500 Sensor Assembly
	Sensor wired incorrectly	Rewire Sensor Assembly properly
Sensor LED blinks, but does not activate flush, solenoid makes buzzing noise, Override Button works (or buzzes with no flush)	High static pressure above 80 psi (552 kPA)	Reduce Static Pressure
	Undersized wiring, insufficient voltage	Reinstall with 18 gauge wiring (minimum), replace transformer
Sensor and Override Button work, Solenoid buzzes (or may trickle water to bowl) but does not activate flush	Solenoid corroded, oxidized or stuck	Replace EL-124-2 Solenoid or rebuild with EL-163-A Solenoid Shaft Assembly Repair Kit
	Damaged Solenoid Shaft Assembly	Replace with EL-163-A Solenoid Shaft Repair Kit
Sensor and Override button work, solenoid clicks, no flush	Actuator cartridge plugged with debris, damaged, or improperly re-assembled	Clean and re-assemble EL-128-A Actuator Cartridge Assembly, or replace

Valve off indicates diaphragm is working properly

# Field Issues & Solutions Not Related to the ESS Exposed Sensor

from most common to least common



Images of uncommon “self-inflicted” issues

# Diaphragm Run-ons



Debris blocking diaphragm bypass



Debris under diaphragm



Degraded diaphragm assembly



Low pressure drop

Symptom	Cause	Solution
Continuous flush with no shut-off	Debris blocking diaphragm bypass	Clean or replace diaphragm (replace inner cover too)
	Debris under diaphragm	Remove debris
	Low pressure drop	Check facility or municipal line pressure
	Diaphragm assembly compromised, cracked plastic guide (due to age)	Replace diaphragm assembly with proper gpf kit

# Piston Run-ons



Debris blocking bypass



Debris under piston



Degraded relief valve seat



Low pressure drop

Symptom	Cause	Solution
Continuous flush with no shut-off	Debris blocking bypass	Clean or replace piston
	Debris under piston	Remove debris
	Degraded relief valve seat	Replace the piston assembly
	Low pressure drop	Check facility or municipal line pressure

In all cases, it's good to flush debris from the line

# No Evacuation - Diaphragm



Low pressure



Improper, low consumption, or urinal diaphragm



Perforated diaphragm



Cover not properly tightened

Symptom	Cause	Solution
No evacuation when flushed (either sensor or override button)	Low pressure (<25 psi / <1.7 bar)	Address plumbing system deficiencies
	Low consumption (LC) or urinal diaphragm installed in older closet	Install correct gpf diaphragm
	Short flushing (perforated diaphragm)	Replace diaphragm
	Cover not properly tightened (DFB - dual filter bypass diaphragm)	Tighten cover

# No Evacuation - Piston



Low pressure



Incorrect piston



Piston lip seal degradation

Symptom	Cause	Solution
No evacuation when handle is depressed	Low pressure (<25 psi/<1.7 bar)	Adjust control stop to increase flow pressure Address plumbing system deficiencies
	Incorrect piston installed	Match piston gpf (Lpf) to fixture gpf (Lpf)
	Piston lip seal degraded	Replace piston assembly

Contact Tech Service for a list of piston kits

# Noise at Shut-off - Piston



High flow pressure


Piston lip seal degradation

Loose plumbing

Symptom	Cause	Solution
"Thump" or "Bang" upon valve shut-off	High flow pressure	Adjust control stop to decrease flow pressure Decrease plumbing system flow pressure
	Piston lip seal degraded	Replace piston assembly
	Loose plumbing	Secure piping properly Check hammer arrestors

# Cover Leak - Piston

Always use a fixed smooth jaw wrench....



Cover not tight enough


Worn cover gasket (Gem)

Worn inside cover (Crown/Naval)

Worn cover gasket (Naval)

Symptom	Cause	Solution
Water leaking from threads beneath flushometer cover	Cover not tight enough	Turn off water and tighten cover
	Worn cover gasket (Gem)	Replace cover gasket (G106)
	Cracked inside cover (Crown)	Replace inside cover (CR124A)
	Worn cover gasket (Naval)	Replace cover gasket (CN76/CN105)

# Inconsistent Flush



Symptom	Cause	Solution
Flush duration is randomly normal, long, or short	Pressure fluctuation within the facility	Check plumbing system pressure and flow capacity
	Actuator Cartridge worn	Replace EL-128-A Actuator Cartridge

# Tailpiece Leak



Tailpiece with O-ring



Sloan H553 O-ring

Symptom	Cause	Solution
Leaking at tailpiece next to control stop	Worn or degraded O-ring	Replace H553 O-ring

Clean the tailpiece O-ring groove and the control stop bore before replacing the O-ring. Use 100% silicone grease (not petroleum-based).

# Vacuum Breaker Leak



Worn vacuum breaker sack



Sloan V651A repair kit



Sloan V551A repair kit

Symptom	Cause	Solution
Dripping from <b>above</b> the vacuum breaker coupling during or after flush	Vacuum breaker sack damaged by over-tightening the vacuum breaker coupling	Clean vacuum breaker tube and replace vacuum breaker sack with V551A or V651A high backpressure VB repair kit
Dripping from <b>below</b> the vacuum breaker coupling during or after flush	Worn or degraded vacuum breaker sack	

Wet the gasket prior to installation and hand tighten then “snug” with wrench

# Control Stop Leak



Control Stop Screw



Sloan H541ASD repair kit




Sloan H543ASD repair kit

Symptom	Cause	Solution
Leaking from control stop adjustment screw	O-ring inside the control stop is worn	Replace with H541ASD control stop repair kit (for older urinals, use H543ASD control stop repair kit)

If unsure of which urinal control stop kit you have for units manufactured between 1964 and 1994, contact Sloan Tech Service

# Spud Flange Coupling Leak



Sloan F3 friction ring



Sloan VBF5 gasket



Sloan F5 gasket

Symptom	Cause	Solution
Leaking from spud flange coupling	The spud flange coupling has loosened	Tighten spud flange coupling
	Spud flange coupling gaskets have become worn	Replace F3 friction ring and VBF5 gasket (1-1/4" or 1-1/2") or F5 gasket (3/4" or 1")

Clean the threads prior to installation, and never use pipe dope or grease!

# Maintenance Recommendations

DOMINICK


SENIOR FIELD & TECHNICAL SUPPORT TECHNICIAN

# Best Practices

- No Teflon tape
- Carry a white towel when removing solenoids to catch and inspect debris
- Tighten couplings and covers by hand, then “snug” with a wrench
- Fixed smooth-jawed wrench
- Avoid compression wrenches
- Carry 100% silicone grease
- Clean threads with a brass bristle brush
- Wet the gaskets before installing
- Clean with soap and water only



Clean with soap and water



Use Genuine Sloan Parts



“Snug” – don’t over tighten

# Summary

- Sloan invented the diaphragm flushometer in 1906 and the piston flushometer in 1928
- ESS Exposed Sensor Flushometers have been a customer favorite since 1978
- Units share many components with Manual Flushometers
- Easy access to Genuine Sloan Parts
- World class Tech Support team
- Vast network of reps to provide assistance
- Follow best practices



# Next Sections in This Series

Part 6 – ESS Concealed  
Electronic Solenoid Sensor

Part 7 – ESS TMO

Part 8 – Hydraulic 900 Series


Part 9 – CX Sensor

Part 10 – CX Manual

Part 11 – Bedpan Washers

## Companion Webinars

- [Piston vs Diaphragm](#)
- [Regal vs Sloan vs Royal](#)
- Flushometer Components 101
- [Converting Manual to Sensor](#)
- [Battery Truths and Myths](#)



Dominick after  
Part 1



Dominick after  
Part 5



Dominick after  
Part 10

# Product Installation & Maintenance Materials

## Product Repair and Maintenance Guides

[Sloan Optima Plus Flushometers](#)

[Sloan Ecos Flushometers](#)

[Sloan Solis Flushometers](#)

## Videos

[Flushometer Basic Maintenance](#)


[Flushometer Tailpiece Removal Instructions](#)


[Control Stop Repair kit Installation](#)

[Ground Joint Control Stops and Adjustable Control Stops Explained](#)

## [Sloan Online Training Materials Catalog](#)

## [Sloan Webinar Series](#)





# Questions?

Find your local Sloan representative for more information

## Sloan Rep Locator tool

- Local code knowledge
- Familiarity with existing sites
- Product knowledge
- Available for onsite consultation

### **Sloan Customer Care Center**

Phone: 800.982.5839

Hours: 7:00 AM - 5:00 PM (CST) Monday – Friday

[customer.service@sloan.com](mailto:customer.service@sloan.com)

### **Sloan Technical Support**

P: 888.756.2614

F: 800.737.3061

[techsupport@sloan.com](mailto:techsupport@sloan.com)



**BBN Sales, Inc.**



# Upcoming Sloan Training Webinars

Click to Register



April 1, 2021

[American Rescue Plan \(ARP\) Funding for Public Restrooms in Educational Facilities](#)



April 8, 2021

[American Rescue Plan \(ARP\) Funding for Public Restrooms in Airports](#)



April 15, 2021

[American Rescue Plan \(ARP\) Funding for Public Restrooms in Restaurants](#)



April 22, 2021

[Sustainability Updates – LEED v4 vs LEED v4.1 and WELL v1.0 vs WELL v2.0](#)

# Training Comments, Questions, or Suggestions?

Andrew Warnes  
Manager – Technical Training  
Sloan Valve Company  
10500 Seymour Avenue  
Franklin Park, IL USA 60131-1259

Office: +1-800-982-5839  
E-mail: [training@sloan.com](mailto:training@sloan.com)  
Web: [sloan.com](http://sloan.com)